



Journal Index 1993

A

Accidents

reduction for 93, Sep.24

AGM

comments, Jun.12
notice, Feb.9, Mar.10
photos, May.27
report, Apr.25

Alarms

safety hazard, Sep.16

Alloy

restoration, Aug.11

B

Battery

charging uprating, Jul.13,
Jul.14
explanation, Aug.18
fitting, May.15
tips, May.15, Aug.18
trickle-charging, Jul.48

Bearings

steering - fitting, Jun.35

Bellypan

(K) K75RT, Jun.16

BMF

BMF Review, Nov.19
BMW Club criticism,
Jun.20,
Chairman, Apr.39, Dec.25
comments, Jul.21, Nov.10
debate on organisation,
Jul.20, Nov.8
review, Nov.20
road tolls fight for bike
rates, Oct.24
Support for 'Make-a-Wish',
Apr.39

BMW

Badges, Jul.22
customising, Nov.16
fake, Dec.20
history, Sep.27
lose domination of London
police bikes, Jun.22
Military Motorcycles, Jul.38

news from Germany,

Feb.16, Apr.23, May.22,
Jun.34, Jul.35, Aug.48,
Oct.37, Nov.23, Dec.38

new Boxer engine(R259)

comments, Feb.10

new F650, Jul.22, Sep.25

Russians/East Germans as
BMW, Oct.14, Dec.20

versus Harley, Jul.46,

Sep.22, Oct.18

warranties, Nov.20

BMW Assurance Scheme

description, Jun.25

BMW Club Europa eV

description, Jan.21

BMW v Harley

in America, Jul.46

Book review

'Women and Motorcy-
cling', Oct.29

Boxers

breaking, Sep.38

review, Jul.30

Brakes

(K) disc problems, Jun.13

(K) warning, Oct.10,
Oct.11

bleeding problems (?!),
Jan.16

cracked disc, Oct.10

hoses - Goodridge, Jan.10

new ABS, Apr.23

pad tests, Nov.21

pedal corrosion, Oct.10

Brittany Ferries

comments, Jan.17

Business Use

advice, Nov.14

Buying

winter buying advice,
Aug.14

C

Camping

comments, Jul.34

Carburetors

(R) Bing mods, Jul.49

(R) Dellorto conversion,
Jul.18

(R) problem, Sep.14

(R) R100 problem, Feb.13

(R) Stromberg diaphragms,
Apr.12

Bing overhaul, Nov.45

Highflow air filters, Aug.24

improving fuel consump-
tion, Sep.13

vibration caused by fairing,
Sep.14

Centre stand

(K) collapse, Aug.32,
Sep.12, Oct.9, Nov.13,
Nov.19

(K) collapse - cure, Oct.16,
Dec.17

(K) treatment, Sep.12
experience, Oct.9, Nov.13,
Nov.19, Dec.17, Dec.19

suggested precautions,
Sep.12, Dec.15, Dec.17

Clothing

100% waterproofs from
BMW, Jun.23

BMW, Apr.25

comments, Jan.18, Mar.16
Frank Thomas - comments,
Feb.10

Frank Thomas, experience,
Feb.10, May.16

Gore-tex cleaning, Aug.10
insurance, Mar.13

leathers at competitive
prices, Jun.23

repair of motorcycle
clothing, Jun.16, Dec.13

waxed cotton repairs,
Jun.16

Club

- assistants to National Officers, Dec.25
- Associate membership, Aug.10, Sep.10, Sep.17
- Club in Europe, Jan.21
- Constitution and Rules, Mar.insert, Oct.23
- Database request/volunteers, Jul.16
- Geoff Wilson, FIM Touring Committee, Dec.24
- History, Jan.24, May.24 Aug.44
- membership levels, Jun.23, Jul.22
- promoting members interests, Oct.22
- NEC and the future, Jan.23
- nostalgic comments, Nov.20
- Section AGMs, Oct.23

Clutch

- (K) problem, Sep.13
- (R) Borg & Beck alternative, Apr.12
- experiences, Sep.13

Coolant

- sight level glass replacement, Jul.14

Corbin seat

- leaks, Jan.11

Corrosion

- frame tubes, Oct.16
- seat brackets, May.16

Covers

- source, Nov.18

Cruise control

- availability, Jul.14

Cylinder head

- (R) 4-valve, Aug.34

D

Dealers

- Averills change to Lind of Norwich, Jul.23
- Classic Restorations move, Nov.22
- Colwyn Bay, new dealer, Jul.23
- dealers vs DIY, Feb.10, May.12, Jun.17, Jun.18; Jul.15, Aug.9

Evington give up BMW, Nov.22

Harmans, recommendation, Mar.16

Moto-Bins, described, Nov.46

praise for service, Jul.16

E

Electrics

- (K) accessory switches, May.30
- high-current switches, Jul.48
- inline fuses, Jul.48
- voltage regulator checking, Aug.16

Engine

(R) R80/7 compared to DAF850, Mar.12

Engine management chips

comments, Mar.17

F

F650

- description, Oct.37
- review, Dec.35

Fairings

(K) bellypan source, Jun.14

Final drive

(R) ratios, Mar.11

Fluorolastomers

safety advice, Jan.11

Fuel Cat

description, Jan.10

Funduro

see F650

Fuses

inline, Jul.48

G

Garages

floor treatment, Feb.12

Gearbox

(R) /6 reliability, Feb.13

General

- 'Bohemian Motorcycles', Oct.30
- 'Life After BMW', Oct.32

H

Handlebars

- (K) KRS mod, Jan.9
- DIY heated grips, Dec.50
- heaters, Apr.19
- heaters of bars rather than grips, Apr.19

Handling

(K) K100RS, Jan.9

Headlamp

- (K) KRS mod, Jan.9
- relay conversion, Oct.47

Health

- custom earplugs, Aug.24, Nov.22
- survey reveals deafness in bikers, Oct.24
- WD40 for arthritis?, Dec.15

Hearing

damage, Jan.14

Helicoiling

advice, Apr.12

Helmets

- Arai - comments, Feb.13
- Arai SZ comments, Jan.13
- Griffin Clubman, May.12
- hair problems, Sep.22
- heated visor repair, Feb.15
- misting, Feb.13
- noise, Jun.22
- oxygen deficiency comments, Jan.14, Jan.17
- preventing ant ingress, Dec.10
- System 2 - comments, Feb.14
- System 2 open/shut, Jun.22, Aug.23
- System 2 problems, Jan.10
- ventilation, Jan.17

Hernias

advice, Apr.14

History

- Part 20, Jan.24
- Part 21, Mar.19
- Part 22, May.24
- Part 23, Aug.44

Horns

Fiamms, Jul.48

I**Ignition**

- BBR chip , Feb.11,
- silicon leads, Jul.49
- Twincoil experience, Jun.12

Instruments

- (K) condensation, Oct.11
- condensation - advice, Nov.16

Insurance, May.17

- classics, Jul.16
- clothing, Mar.12
- comments, Jul.17
- Data-Tagging to reduce costs, Dec.26
- European travel, Aug.22
- green cards, Feb.10
- Norwich Union ends knock for knock, Aug.23
- rebate dissatisfaction, Jun.15, Jul.17

Intercoms

- Peltor - problem, Feb.14

International Motorcycle Show, Jan.23**Instruments**

- water ingress, Nov.16

K**K1**

- limited edition, Nov.20
- panniers, Apr.11, Jul.12
- touring, Oct.14

K100

- backfiring, Jan.19, Sep.16
- comments, Jan.18
- condensation, Sep.15
- LT versus K1100LT, Nov.12
- reliability, Jul.12
- vibration, Mar.16

K100LT

- lubrication, Mar.17
- vibration, Mar.16

K100RS

- appreciation, Oct.43
- brake hoses - Goodridge, Jan.9
- Bridgestone tyres, Jan.9
- Comfort seat, Jan.9
- experiences, Nov.39
- fitting bars from 16v, Jan.9

- handlebar mod, Jan.9
- handling, Jan.9
- headlamp mod, Jan.9
- mods, Mar.13, Nov.39

K100RS 16v

- tyres, Mar.16

K100RT

- appreciation, Oct.42
- suspension, Oct.12

K1100LT

- comments, Nov.12
- screen adjustment, Jul.11

K1100RS

- impressions, Jul.10
- review, May.20

K1100RS/R1100RS

- Motorrad comparison, Aug.48

K75

- Motorrad comments, Feb.16

K75RT

- bellypan, Jun.15
- brake disc problems, Jun.13
- comments, Jan.12, Feb.16

K75S

- comments, Feb.16
- tyres, Jan.16
- vibration, Aug.21, Sep.23

L**Legislation**

- 100bhp limit, Jun.22, Sep.24, Nov.20, Dec.26
- availability of documents, May.19
- air-bags, possible legislation, Jun.22
- fines for traffic offences, Jul.22
- GATSO, Jul.23, Nov.38
- laser detectors, Nov.22
- leg protectors, Nov.22
- motorway tolls, Dec.26
- Type Approval, Jul.23

Lights

- running lights, Jul.14

Lubrication

- (K) K100LT, Mar.17
- grease dispensers, May.17
- oil filters, Oct.13

M**Military motorcycles**

- WWII, Jul.38

N**NCM**

- February, Mar.30
- May, Aug.27
- November, Dec.28

O**Obituary**

- 'Lady' of Slocombes, May.18
- Colin Overton, Jun.18
- Gilbert Hicks, May.11
- Mike Wardell, Jul.23
- Tony Crampin, Mar.18

Oil

see Lubrication

P**Painting**

- powder coating at discount, Jul.23
- recommendation, Nov.17

Panniers

- hinges, Feb.14
- K1, Jul.12
- K1 mods, Apr.11

Parts

- (R) stainless pushrod tubes, Jun.23, Sep.25
- (R) stainless valves, Jul.23
- (R) starter parts ex-Fiesta, Aug.16
- alternative, Apr.12
- boxer breaking, Sep.38
- cruise control, Jul.14
- electrical components identified, Jul.14
- Harman 16v chip, Jan.27
- pre-1969 items, May.34
- pre-69, May.34
- prices, Jan.9

Powder coating

- service, Jul.23

Photography

- courses in France, Jan.33
- illustrations of your bike, Jun.21

Plating /Polishing

Arnwood Engineering,
Feb.41

R

R100

carburettor problem,
Feb.12
engine specs, Dec.38

R100R

comments, Jan.18

R100RS

review, Mar.20

R1100RS

comments, Nov.12
Motorrad review, Jul.34
review, Oct.36, Dec.40

R1100RS/K1100RS

Motorrad comparison,
Aug.48

R45

appreciation, Nov.31

R65LS

appreciation, Jun.28

R80/7

DAF 850 engine comparison,
Mar.12

R80RT

tyres, Jan.16

R90S

restoration, Nov.29

Racing

Nürburgring school,
Nov.24

Rallies

BMF, Jul.19
Ceinewydd, Aug.30
comments, Nov.14
Dreaming Spires, Jul.28
Festival of 1,000 Bikes,
Nov.28
FIM Motocamp Sardinia,
Aug.42
Hippo, Jan.26
IOM Assembly, Apr.20
Knebworth, Dec.32

Recipes

Barbeque sauce, Sep.37

Renovation

hints and tips, Feb.21

Roads

lovely ones, Mar.11

S

Safety

during thunderstorms,
May.32

Screen

(K) K1100LT adjustment,
Jul.11

Seats

(K) KRS Comfort seat, Jan.9
Corbin - comments, Feb.14
Corbin leaks, Jan.11
Corbin leaks - cure, Nov.17

Security

lock carrier, Jul.49

Speeding

new ways to be caught,
Nov.38

Starting

(K) problems cold, Sep.26

Suspension

(K) K100RT, Oct.12
review, Oct.37

Switches

high-current, Jul.48

T

Tax avoidance

advice, Nov.14

Timing chain

fitting, Aug.10
problems solved, May.29
replacement, May.13

Touring

Antipodes, Sep.28
Australia, Sep.21
Bohemia, Apr.27, Jul.20
Cyprus, Apr.14
Europ Assistance, Jun.21
Europe, Feb.23
France, May.23
K1, Oct.14
Luxembourg, Feb.18
Scandinavia, Feb.30
Scotland, Oct.25, Dec.44,
Dec.47
Spain/France, Aug.36

Trailers

review, Jul.24

Training

advanced, Jun.14

TT

report, Aug.49

Type Approval

threat, Jul.23

Tyres

(K) Bridgestone on KRS,
Jan.9
(K) K100RS 16v comments,
Mar.16
(K) K75S, Jan.16
(R) R80RT, Jan.16
comments, Feb.12, Jul.16,
Jul.19
fitting, Sep.21
fitting without tears, Jun.32
puncture prevention,
Sep.11
puncture problems, Jun.31
recommendations, Nov.11
tubeless repair kits, Apr.22
valve safety, Dec.19

V

Vibration

(K) K100LT, Mar.17=6
(K) K75S, Aug.21, Sep.23

Visors

heated visor repair, Feb.15

Voltage regulator

checking, Aug.16

W

Wheels

(R) pre-82 warning, Nov.9
puncture problems, Jun.31

Wind noise

comments, Mar.16